



Instructions for Model SB48-TC Super Bender® and TB60-TC Top Bender®

Automatic Simplified Mode - single bend program


 **WARNING! Thoroughly read operators manual before attempting to operate machine**
(Machine must be connected to correct power source before switching power on! **DO NOT USE** extension cord.)

Execute a single programmed bend.

1. Press Automatic icon from home page or from service bar.
2. The following page will open:







3. Bend number area: Press field and use numerical keypad to enter number 0 (zero). Must be zero to run simplified program.
4. Desired bend angle and Springback return angle: Press fields to enter values from numerical keypad. (Can be edited later.)



"C"-axis will rotate until the software limit in machine data is reached. Alarm is generated.

Alarms area: Alarm symbol  will be displayed.

5. Press and hold Bend pedal  or  icon on display to make a bend; the status bar will be green. "C"-axis will start moving at speed indicated in Speed area.
6. Machine will automatically stop movement when set value is reached in Automatic Simplified mode.
7. Return "C"-axis to zero after bending by pressing and holding  Return pedal or  icon.



If you should press opposite pedal/icon during a rotation machine will immediately stop movement without generating an alarm.



CML USA, Inc. • (563) 391-7700
www.ercolina-usa.com

Setting Springback Value 


Setting Springback Value

Understanding springback

- Desired angle **b** represents value in degrees to be obtained after bending.
- Springback angle **a** represents angle in opposite direction of bend in which material returns after being released from the tools.
- The **y** angle that represents movement of "C"-axis

Springback angle is difference in degrees between desired bending angle **b** and bending angle **y** obtained without considering the elasticity of processed material $a = y - b$

To obtain desired angle total bend rotation of "C"-axis equals $y = a + b$.



Use goniometer and measure angle obtained after test bend to determine value of springback return. The difference must be entered in springback return field.

Note: Angle measured with goniometer will be different from rotation value of the "C"-axis because of material elasticity. Make multiple bends and measure angle of each to determine actual springback return angle required.

Note: Rotation angle of "C"-axis cannot exceed 210°. If value entered in springback return field exceeds 210° the angle field will be automatically reduced to maintain limit.

By setting **b** = 200, if you enter **a** = 20 and therefore $a + b = 220$, the system automatically reduces the value of **b** and sets it equal to 190°

Note: entering a value between 0% and 10% in the Speed field, the machine will always move at a minimum speed of 10% while displaying the entered value.

